



Photo 3 - Looking north at a gully on the south shore near the end of Sutherland Road. A recent slide has taken place, initiating on the east side of the gully head. Slide debris from past events has built up a debris cone at the base of the slope.