



Photo 4 - Looking north at the erosion face in Quadra Sand on the west side of Garnet Point. Eroded sand accumulates at the base of the slope and is removed by wave action. Intense erosion here is ascribed to refracted storm waves from the southeast. The Geological Survey of Canada measured 0.38 m of bluff crest retreat in 1 year at this location.